

## Acil SAHA GÜVENLİK UYARISI

Cihaz: **Radifocus® Introducer II, Radifocus® Introducer II M coat ve Glidesheath Slender™**  
Sorun: **Ürünün sterilitesinin bozulmasına neden olabilecek olası paket bütünlüğü kaybı**  
Referans: **FSN 1701 2017-05**  
İşlem: **İade**

**Dikkat:** Hastane Başhekimliği, Kateterizasyon Laboratuvarı, Klinikler ve Tıbbi Personel

### SORUNUN AÇIKLAMASI

Merkezi Japonya'da bulunan Terumo Corporation, transradial ve transfemoral girişim prosedürlerini desteklemek için kullanılan Radifocus Introducer II, Radifocus Introducer II M coat ve Glidesheath Slender'in belirli lotlarını dünya genelinde gönüllü olarak geri çağırılmaktadır.

Geri çağırmanın nedeni, ürünün sterilitesinin bozulmasına neden olabilecek olası paket bütünlüğü kaybıdır. Bu sorun Terumo tarafından yapılan rutin denetim sırasında kitin soyularak açılan torbasının düzgün kapatılmamış olduğu gözlemlendiğinde belirlenmiştir.

### ETKİLENEN CİHAZ HAKKINDAKİ BİLGİLER

Etkilenen cihazların listesi (parça ve lot numaraları) için bkz. **EK I**.

### OLASI TEHLİKE

Bu konuya ilişkin bir müşteri şikayeti veya bildirilen bir hasta yaralanması yoktur. Olası kusur oranının %0,02'den az olduğu tahmin edilmektedir. Kusurun niteliği ve ürün performansına etkisi göz önünde bulundurulduğunda hastaya zarar verme olasılığı da düşüktür. Paket bütünlüğü bozulan ürünler üzerinde gerçekleştirilen sterilite testlerinin hepsi negatiftir (= mikroorganizma gelişimi yoktur).

Yaptığımız tüm işlerde hasta sağlığını ve güvenliğini taahhüt ederiz. Bu nedenle ihtiyati tedbir olarak bu gönüllü geri çağırma (sahadan kaldırma) kararını verdik.

### DÜZELTİCİ EYLEM

Terumo ilgili müşterileri sorun hakkında uyarmakta, onlardan şüpheli ürünleri kullanmayı bırakmalarını ve stoklarında kalan üniteleri iade etmelerini istemektedir.

### MÜŞTERİ TALİMATLARI

- 1) Bu Saha Güvenlik Uyarısı'nı inceleyin ve tüm kullanıcıların bu uyarı konusunda bilgilendirildiğinden emin olun.
- 2) Ek I'de listelenen parça ve lotlardan geriye kalan tüm kullanılmamış üniteleri derhal belirleyin ve ayırın.
- 3) Ekteki listedeki kullanılmamış ünitelerin numarasını ilgili yanıt formunda işaretleyin ve bu formu mümkün olan en kısa sürede formda yer alan e-posta adresine veya faks numarasına gönderin.

- 4) Terumo Europe temsilciniz, ürünün derhal toplatılmasına ilişkin işlemleri organize etmek üzere sizinle iletişime geçecek ve müşteri hizmetleri de gerekirse bir alacak dekontu hazırlayacaktır.

Bu *Saha Güvenlik Uyarısı* belgesinin ilgili ulusal Yetkili Kuruma da iletilmiş olduğunu onaylıyoruz.

Herhangi bir sorunuz ya da kaygınız varsa lütfen bizimle veya yerel Terumo temsilcinizle iletişim kurun.

Julie Godeau  
Bo Timmermans  
TERUMO EUROPE N.V.  
European Emerging Markets - Division  
Tel: +32 16 38 13 26  
Tel: +32 16 38 13 09  
Fax: +32 16 40 02 49  
Julie.Godeau@terumo-europe.com  
Bo.timmermans@terumo-europe.com



Fien Aerts  
Mevzuat ve Kalite Başkan Yardımcısı  
Terumo Europe NV  
Leuven, Belçika

**Ek I - Etkilene cihazlar hakkında bilgiler (sayfa 1/4)**

Ürün kodu	Açıklama	Etkilene lot numaraları
RS*A10K10SQ	Radifocus® Introducer II	161101, 161207
RS*A11K10SQ	Radifocus® Introducer II	161129, 161207, 170113, 170116
RS*A40G05SQ	Radifocus® Introducer II	161122, 161202, 170112
RS*A40G07SQ	Radifocus® Introducer II	161117
RS*A40K10AQ	Radifocus® Introducer II	161118
RS*A50G07SQ	Radifocus® Introducer II	170109
RS*A50K10SQ	Radifocus® Introducer II	161212
RS*A60G05SQ	Radifocus® Introducer II	161031, 161130
RS*A60G07SQ	Radifocus® Introducer II	170109
RS*A70K10SQ	Radifocus® Introducer II	161031
RS*A90K10SQ	Radifocus® Introducer II	161109, 161202, 170109, 170202
RS*B10K10MQ	Radifocus® Introducer II	161213
RS*B10N10MQ	Radifocus® Introducer II	161128, 161208, 170110
RS*B10N25AQ	Radifocus® Introducer II	161104
RS*B11K10MQ	Radifocus® Introducer II	161107, 161209, 170116
RS*B11N10MQ	Radifocus® Introducer II	161114, 161212, 170201, 170202
RS*B11N10SQ	Radifocus® Introducer II	161111, 161212, 170113
RS*B11N25AQ	Radifocus® Introducer II	161115, 161212
RS*B40G07SQ	Radifocus® Introducer II	161202
RS*B40K10AQ	Radifocus® Introducer II	161209
RS*B50G07SQ	Radifocus® Introducer II	161201
RS*B60N10MQ	Radifocus® Introducer II	161125, 161222
RS*B90K10MQ	Radifocus® Introducer II	161102, 161201
RS*B90N10MQ	Radifocus® Introducer II	161103, 161206
RS*B90N10SQ	Radifocus® Introducer II	161111, 161206, 170113
RS*B90N25AQ	Radifocus® Introducer II	161108, 161202, 170110
RS*R50N10MQ	Radifocus® Introducer II	161124
RS*R60N10MQ	Radifocus® Introducer II	161129, 161213
RS*R80N10MQ	Radifocus® Introducer II	161207
RS*R90N10MQ	Radifocus® Introducer II	161108, 161121, 161205, 170201

## Ek I - Etkilene cihazlar hakkında bilgiler (sayfa 2/4)

Ürün kodu	Açıklama	Etkilene lot numaraları
RS+A40G07SQ	Radifocus® Introducer II	161124
RS+A40G10SQ	Radifocus® Introducer II	161125
RS+A40K10AQ	Radifocus® Introducer II	161121
RS+A50G07SQ	Radifocus® Introducer II	161125, 161212
RS+A50K10SQ	Radifocus® Introducer II	161128
RS+A60G07SQ	Radifocus® Introducer II	161206
RS+A60K10AQ	Radifocus® Introducer II	161126
RS+A60K10SQ	Radifocus® Introducer II	161126, 161209
RS+A70K10SQ	Radifocus® Introducer II	161124
RS+A80K10SQ	Radifocus® Introducer II	161128
RS+B40K10AQ	Radifocus® Introducer II	161121
RS+B40K10MQ	Radifocus® Introducer II	161122, 161209
RS+B40K10SQ	Radifocus® Introducer II	161123
RS+B50K10MQ	Radifocus® Introducer II	161123, 161214
RS+B50N10MQ	Radifocus® Introducer II	161128, 161206
RS+B50N10SQ	Radifocus® Introducer II	161126
RS+B50N25AQ	Radifocus® Introducer II	161126
RS+B60G07SQ	Radifocus® Introducer II	161122
RS+B60K10MQ	Radifocus® Introducer II	161129, 161212, 161214
RS+B60N10MQ	Radifocus® Introducer II	161115, 161130, 161210
RS+B60N10SQ	Radifocus® Introducer II	161130
RS+B60N25AQ	Radifocus® Introducer II	161129
RS+B70K10MQ	Radifocus® Introducer II	161123, 161206
RS+B70N10MQ	Radifocus® Introducer II	161124
RS+B70N10SQ	Radifocus® Introducer II	161124
RS+B70N25AQ	Radifocus® Introducer II	161125
RS+B80K10MQ	Radifocus® Introducer II	161126
RS+B80N10MQ	Radifocus® Introducer II	161128
RS+B80N10SQ	Radifocus® Introducer II	161128
RS+B80N25AQ	Radifocus® Introducer II	161129
RS+R40K10MQ	Radifocus® Introducer II	161122
RS+R50N10MQ	Radifocus® Introducer II	161126
RS+R60N10MQ	Radifocus® Introducer II	161130, 161203
RS+R70N10MQ	Radifocus® Introducer II	161125, 161212
RS+R80N10MQ	Radifocus® Introducer II	161128

**Ek I - Etkilenen cihazlar hakkında bilgiler (sayfa 3/4)**

Ürün kodu	Açıklama	Etkilenen lot numaraları
RM*AF5G10HQW	Radifocus® Introducer II M Coat	161103
RM*AF5J10SQW	Radifocus® Introducer II M Coat	161108, 161216
RM*AF5J16SQW	Radifocus® Introducer II M Coat	161111, 161125
RM*AF5J25SQW	Radifocus® Introducer II M Coat	161115, 161214
RM*AF6J10SQW	Radifocus® Introducer II M Coat	161021, 161024, 161107, 161121 161122, 161123, 161202, 161216 170109,170110, 170119, 170120 170123, 170124, 170125
RM*AF6J25SQW	Radifocus® Introducer II M Coat	161114, 161129, 161130, 161213 161228, 170223, 170224, 170302
RM*RF5F10PQ	Radifocus® Introducer II M Coat	161024, 161109, 161128,161214 170126, 170201
RM*RF5F16PQ	Radifocus® Introducer II M Coat	161114, 161212
RM*RF5F25PQ	Radifocus® Introducer II M Coat	161114
RM*RF5J10PQ	Radifocus® Introducer II M Coat	161110, 161209, 170112
RM*RF5J16PQ	Radifocus® Introducer II M Coat	161115, 161213, 170113
RM*RF5J25PQ	Radifocus® Introducer II M Coat	161111, 161130, 161209, 170116
RM*RF6F10PQ	Radifocus® Introducer II M Coat	161025, 161026, 161027, 161028 161111, 161223, 161226, 170113 170202, 170203, 170208
RM*RF6F16PQ	Radifocus® Introducer II M Coat	161027, 161108, 161130
RM*RF6F25PQ	Radifocus® Introducer II M Coat	161031, 161110, 161212, 161226 170130, 170131, 170208
RM*RF6J10PQ	Radifocus® Introducer II M Coat	161109, 161213, 161219, 170131
RM*RF6J16PQ	Radifocus® Introducer II M Coat	161028, 161115, 161128, 161209 170118
RM*RF6J25PQ	Radifocus® Introducer II M Coat	161031, 161102, 161209, 161228 170127

## Ek I - Etkilene cihazlar hakkında bilgiler (sayfa 4/4)

Ürün kodu	Açıklama	Etkilene lot numaraları
RM*ES5F10SQR	Glidesheath Slender™	161108, 161202, 170110
RM*ES5J10SQ	Glidesheath Slender™	161103, 161118, 161201
RM*ES6F10SQR	Glidesheath Slender™	161021, 161109, 161128
RM*ES6J10HQS	Glidesheath Slender™	161124, 170116, 170202
RM*ES6J10PQ	Glidesheath Slender™	161109, 161125, 161205
RM*ES6J10SQ	Glidesheath Slender™	161223
RM*ES6J16HQS	Glidesheath Slender™	170111, 170206, 170307
RM*ES6J16PQ	Glidesheath Slender™	161128
RM*ES6J16SQ	Glidesheath Slender™	161110, 161125
RM*ES7F10SQR	Glidesheath Slender™	161115
RM*RS5C10PQ	Glidesheath Slender™	161104, 161123, 161124, 161201 170120, 170201
RM*RS5F10PQ	Glidesheath Slender™	161107, 161201, 161227, 170127 170201
RM*RS5F16PQ	Glidesheath Slender™	161108, 170202
RM*RS6C10PQ	Glidesheath Slender™	161024, 161111, 161214
RM*RS6F10PQ	Glidesheath Slender™	161024, 161025, 161101, 161104 161107, 161116, 161117, 161118 161121, 161122, 161123, 161202 161215, 161216, 161219, 161220 161221, 161222, 161223, 170110 170111, 170112, 170117, 170118 170119, 170120, 170125, 170126 170203
RM*RS6F16PQ	Glidesheath Slender™	161031, 161110, 161114 161213
RM*RS6J10PQ	Glidesheath Slender™	161028, 161108, 161111 161115, 161208, 161209 170112, 170113, 170127 170130, 170131
RM*RS6J16PQ	Glidesheath Slender™	161026, 161114, 161128 161207, 170125
RM*RS7F10PQ	Glidesheath Slender™	161031, 161109, 161209 161212
RM*RS7F16PQ	Glidesheath Slender™	161115, 161129
RM*RS7J10PQ	Glidesheath Slender™	161129
RM*RS7J16PQ	Glidesheath Slender™	161114, 161130

## Saha Güvenliđi Uyarısı - MÜŞTERİ CEVAP FORMU

Cihaz: Radifocus® Introducer II, Radifocus® Introducer II M coat ve Glidesheath Slender™

Sorun: Ürünün sterilitesinin bozulmasına neden olabilecek olası paket bütünlüğü kaybı

Referans: FSN 1701 2017-05

İşlem: İade

Lütfen doldurun, imzalayın ve faks ya da e-posta ile geri gönderin::

Kime:

E-posta/Faks:

Müşteri numarası	
Hastane Adı	
Şehir	
Ülke	

Kayıtlarımız, şüpheli ürünlere dahil cihazlardan aldığınızı göstermektedir.

Hastanenin kendi envanteri		
Referans	Parti	Adet

Yanıtlayan [Daktilo Harfleriyle]	
Ünvan	
Telefon Numarası	
İmza	
Tarih	

FSN1701A [TR]